



Type	Motor Yacht	Classification	RINA
Top	--	Class Type	Commercial
Model	Classic 115	Builder	BENETTI YACHTS
Manuf. Year	2003	Naval Architect	--
Refit Year	2022	Interior Design	Francois Zuretti
LOA	114' 8" (34.95m)	Hull	GRP
Beam	24' 8" (7.52m)	Deck	Teak
Draft Min/Max	-- / 6' 6" (1.98m)	Engines	2x, CAT, 3412E, 1400 HP
GRT	--	Max Speed	17 Knots
Fuel	35000 L (9246.02 Gal)	Cruise Speed	14 Knots
Water	6200 L (1637.87 Gal)	Range	3200
Flag	United Arab Emirates	Accommodations	5 strms

ASKING PRICE: (\$6,536,634 USD est.)
€5,600,000 EUR

Aerial View



Aerial View



Aerial View



Upper Deck Aft



Upper Deck Aft



Upper Deck Aft



Sun Deck















DSC06897



DSC06605-HDR



DSC06554



DSC06788



DSC06806



Refit

MY DXB 35m Refit 2021-2022

Interior

1. New ceilings
2. New flooring (new marble and carpets)
3. New fabrics (cabins)
4. New electrical blinds (main / upper salons + master cabin)
5. Automation of lights, curtains, AV
6. New furniture (sofas, tables, chairs)
7. Full refurbishing of crew area (paint, varnishes, mattresses, bathrooms, galley seating area)
8. New Miele cooktop in galley
9. Additional new dishwasher in upper salon
10. New art pieces (salons, corridors, cabins)
11. New TVs (2 salons + all cabins)
12. Insulation foam (inside bulkheads, technical lockers, bilges)
13. Bar tops (new marble)
14. All interior design reviewed and refreshed
15. Wheelhouse's electronics reviewed and updated
16. New surround sound system

Exterior

1. Full paint (hull and superstructure)
2. New teak on sundeck
3. New teak step to bow area
4. New teak on bow area
5. New teak on swim platform
6. New teak jacuzzi perimeter
7. Full teak deck recaulking and sanding
8. Converted step lights from spot lights to hidden LED strip lights
9. New lighting (ceiling and courtesy)

10. All new upholstery (all decks)
11. New upper deck extendable dining table + seating area
12. Full polishing of stainless-steel items
13. New outdoor furniture
14. New CCTV system installed
15. New IP Camera installed in stern
16. New sun awning
17. New Seabob F5S

Under hull

1. New depth sounder transducer
2. New sea lights (underwater lights) supply and installation
3. Full sanding of the hull bottom and application of primer + primer antifouling + antifouling